

# Devices - Keypad

Ben Graham submitted this tip for getting the PIN codes to update on the Door Controller:

In MC6 we are required to restart services for Door Controllers to take PIN codes. This was the most likely cause because the PIN codes would not work on any door. I set a PIN to 1876# and tested with that after restarting services and door does work as intended.

---

Revision #3

Created 11 November 2022 21:45:46 by Sarah Davis

Updated 11 November 2022 21:58:54 by Sarah Davis